




Established 1930
Distributors of new & used workshop Equipment

D164
RF-19V
Pedestal Drill

INSTRUCTION & PARTS MANUAL

1-9-11

[illegible]

VARIABLE SPEED DRILL PRESS



19V



19VTM

MODEL 19V / 19VTM INSTRUCTION MANUAL

19V(AC)-388HF-110831-R0

WARNING !

Some dust created by power sanding, sawing, grinding, drilling, and other construction activities contains chemicals known to the State of California to cause cancer, birth defects or other reproductive harm. Some examples of these chemicals are:

- Lead from lead-based paints.
- Crystalline silica from bricks, cement and other masonry products.
- Arsenic and chromium from chemically-treated lumber.

Your risk from these exposures varies, depending on how often you do this type of work. To reduce your exposure to these chemicals: Work in a well ventilated area, and work with approved safety equipment, such as those dust masks that are specially designed to filter out microscopic particles.

**WARNING: FAILURE TO FOLLOW THESE RULES
MAY RESULT IN SERIOUS PERSONAL INJURY**

As with all machinery there are certain hazards involved with operation and use of the machine. Using the machine with respect and caution will considerably lessen the possibility of personal injury. However, if normal safety precautions are overlooked or ignored, personal injury to the operator may result.

This machine was designed for certain applications only. We strongly recommends that this machine NOT be modified and/or used for any application other than for which it was designed. If you have any questions relative to its application DO NOT use the machine until you contact with us and we have advised you.

Your machine might not come with a power socket or plug. Before using this machine, please Do ask your local dealer to install the socket or plug on the power cable end.

2.SAFETY RULES FOR ALL TOOLS

A. USER:

1. **WEAR PROPER APPAREL.** No loose clothing, gloves, rings, bracelets, or other jewelry to get caught in moving parts.

Non-slip foot wear is recommended. Wear protective hair covering to contain long hair.

2. **ALWAYS WEAR EYE PROTECTION.** Refer to ANSLZ87.1 standard for appropriate recommendations.

Also use face or dust mask if cutting operation is dusty.

3. **DON'T OVERREACH.** Keep proper footing and balance at all times.

4. **NEVER STAND ON TOOL.** Serious injury could occur if the tool is tipped or if the cutting tool is accidentally contacted.

5.**NEVER LEAVE TOOL RUNNING UNATTENDED. TURN POWER OFF.** Don't leave tool until it comes to a complete stop.

6. **DRUGS, ALCOHOL, MEDICATION.** Do not operate tool while under the influence of drug, alcohol or any medication.

B. USE OF MACHINE:

1. **DON'T FORCE TOOL.** It will do the job better and be safer at the rate for which it was designed.

2. **USE RIGHT TOOL.** Don't force tool or attachment to do a job for which it was not designed.

3. **SECURE WORK.** Use clamps or a vise to hold work when practical. It's safer than using your

hand frees both hands to operate tool.

4. **USE RECOMMENDED ACCESSORIES.** Consult the owner's manual for recommended accessories. The use of improper accessories may cause hazards.

5. **AVOID ACCIDENTAL STARTING.** Make sure switch is in “**OFF**” position before plugging in power cord.

C. ADJUSTMENT :

MAKE all adjustments with the power off. In order to obtain the machine. precision and correct ways of adjustment while assembling, the user should read the detailed instruction in this manual.

D. WORKING ENVIRONMENT:

1. **KEEP WORK AREA CLEAN.** Cluttered areas and benches invite accidents.

2. **DON'T USE IN DANGEROUS ENVIRONMENT.** Don't use power tools in damp or wet locations, or expose them to rain. Keep work area well-lighted.

3. **KEEP CHILDREN AND VISITORS AWAY.** All children and visitors should be kept a safe distance from work area.

E. MAINTENANCE

1. **DISCONNECT** machine from power source when making repairs.

2. **CHECK DAMAGED PARTS.** To read every details of trouble shooting, repair it very carefully and make sure the operator won't get injure and damage the machine.

Thank you for purchasing the **19V** Machine. If properly cared for and operated, this machine can provide you with years of accurate service. Please read this manual carefully before using your machine.

3.TRANSPORTATION OF MACHINE:

Unpacking

1. Transportation to desired location before unpacking, please use lifting jack.(Fig. B)
2. Transportation after unpacking, please use heavy fiber belt to lift up the machine.




Fig. B

ALLWAYS KEEP PROPER FOOTING & BALANCE WHILE MOVING THIS MACHINE.

Installation:

As this machine weights 200 kgs. It is recommended that the machine shall be transported, with help of lifting jack.


Transportation Recommendation:

- (1) Tighten all locks before operation.
- (2) **ALWAYS** Keep proper footing & balance while moving this 200 kgs machine, and only use heavy duty fiber belt to lift the machine as Fig. A
- (3) **TURN OFF** the power before wiring, & be sure machine in proper grounding, Overload & circuit breaker is recommended for safety wiring.
- (4) Fix machine on the floor by fixing 4 screws to base holes, after machine is balanced.
- (5) **CHECK** carefully if main shaft in clockwise direction while running test, if not, reverse the wiring per circuit diagram, then, repeat the test till spindle direction is correct.
- (6) **KEEP** machine always out from sun, dust, wet, raining area.



Fig.A

4.MINLMUM ROOM SPACE FOR MACHINE OPERATION




5.SPECIFICATIONS:

Nature	19V
Range of spindle speeds	0~2000rpm
Drilling capacity in mild steel	28mm
Tapping capacity in mild steel	18mm
Max. Spindle nose to column surface	252mm
Max. Spindle nose to table	678mm
Max. Spindle nose to base	1225mm
Spindle taper	MT3
Spindle travel	120mm
Quill diameter	Ø55mm
Column diameter	Ø100mm
Working surface of table	420*470mm
Number of T-slots	2
T-slot size	16mm*26mm
Packing Measurement (L*W*H)	940mm*750mm*1867mm
Motor	Max.1HP 230V 3Ø
Net / Gross weight	200 / 230 Kgs
20`container Q`ty	18 sets

6.MAIN PARTS:

- | | | |
|-------------------------------|--------------------------|----------------|
| 1. Belt & pulley safety guard | 2. Handle | 3. Motor |
| 4. Graduated base fixed grip | 5. Lifting rocker | 6. Column |
| 7. Switch | 8. Spring adjusting knob | 9. Speed chart |
| 10. Graduated scale | 11. Main table | 12. Base |




STANDARD ACCESSORIES

1. 1/2"(13mm) Keyless drill chuck. JT6 or B16 x1
2. Punch key. x1
3. Paint(Can) x1
4. Carbon Brush. x4
5. Wrench M4 x1 M5 x1

7.Switch Functions:

A.	Power Indicator Light	Indicator Power on/off
B.	Forward/Reversion Switch	The spindle rotate as clockwise while button turn right, rotate as anti-clockwise while turn left..
C	Main Switch	For power supply control
D	Speed Dial	For adjusting desired speed
E	Start Button	For spindle running
F	Stop Button	For spindle stop
G	Emergency Stop/Release Button	Press this button when in emergency, or stopping spindle Movement. Re-start by releasing the button.



In Drilling Operation

1. Turn the main power switch (C) to ON, the “stand-by” light on (A), power is ready to operate.
2. Please press (B) button when you start machine (the spindle rotate as clockwise while button turn right, rotate as anti-clockwise while turn left.).
3. Press spindle start button to run the spindle. (E)
4. Use speed dial D for desired speed. Speeds can be seen on LCD screen.
5. Pull down spindle travel bar for drilling work piece.
6. Press stop button F to stop the spindle running.
7. When in emergency, press EMERGENCY STOP G to completely stop the machine movement.

PS.

1. If the overload cause to the jump off, please disconnect the power and restart again.
2. If no movement when reconnecting the power, please check the fuse in control box.
3. Do not use power cable longer than 10 meters. Do not curve the cable, be sure to use wire cable diameter over 16 gauge.


Variable Speed Selection Chart

Drill Bit		Aluminum & Alloys	Copper Alloys	Alloy Steels
3.2	1/8" Dia.	2000	1833-2000	611-2000
6.3	1/4" Dia.	2000	966-2000	305-1298
9.5	3/8" Dia.	2000	611-1782	203-965
12.7	1/2" Dia.	2000	458-1336	152-649
15.8	5/8" Dia.	1224-1834	366-1069	122-519
19	3/4" Dia.	1016-1528	305-891	101-432
22.2	7/8" Dia.	876-1310	261-763	87-371
25.4	1" Dia.	764-1146	229-668	76-324
28.5	1-1/8" Dia.	680-1018	203-594	67-288
31.7	1-1/4" Dia.	612-840	183-534	65-259

- This chart is a general reference for a 90° cut in the workpiece using HSS (High-Speed Steel) tools. And it's easy to reduce a half of RPM if you want to use the HCS (High-Carbon Steel) tools.

HOW To Change Motor Carbon Brush

1. Make sure Main Switch is completely shut off, and no danger of electrical shark.
2. Loose the screw on motor protection cover, follow the photo direction, fix the motor protection cover in proper position by screw.
3. Replace the old brush by a new one.
4. Set back the motor protection cover by reversed procedure.
5. Turn on the power, run the machine to make sure the smoothness.




8.HOW TO HANDLE THE SPINDEL SPEED VARIABLE SPEEDS

This machine was designed by 2 step (high and low) variable speed operation.
Make sure which step you are in before operating the machine.

How to change the speed step:


1. Open belt cover on top of the machine (A).
2. Loosen the fix shaft (B).
3. Change belt step on pulley (C).
4. Lock the fix shaft (B).
5. Close back the belt cover (A).
6. Turn the speed dial to desired speed




9.RETURN SPRING ADJUSTMENT

The return spring is adjusted at the factory and should not need adjustment. If it does, follow These steps.

1. **Disconnect drill press from power source.**
 2. **Loosen plum screw (B) approximately 5mm, Do not remove.**
 3. **Firmly hold coil spring cover (A); pull out and rotate until pin on return spring plate engages with next notch in coil spring cover (A). Turn counterclockwise to increase tension and clockwise to decrease tension.**
- CAUTION: Improper operation might get injured.**



10.SWIVEL VISE TABLE FUNCTION



- A. Swivel vise Table : Working with clamping.
- B. Lock Blot : After Swivel to fix working table & vise.
- C. Vise Table Handle : Move vise and clip workpiece.
- D. Swivel Scale : Swivel Angle & Index.
- E. Vise : Clip workpiece.
- F. T-Screw : Fix position for complete vise.
- G. Position Pin : Index Fixed.

11.Trouble Shooting:

(1) No running after switch on:

- (a) Main switch interruption while volts irregular - Adjust input voltage and draw back the main switch.
- (b) In case of too much current, the overload relay jumps away automatically - Press the overload relay, and it will return to the correct position.

(2) Motor overheat and no power:

Power will be automatically shut off.

when spindle is overworked. Turn on the main switch to restart the machine.

- (a) Overload - Decrease the load of feed.
- (b) Lower voltage - Adjust to accurate voltage.
- (c) Spoiled contact point of magnetic switch - Replace with new one.
- (d) Break down of overload relay - Connect it or replace with new one.
- (e) Motor is poor - Replace with new one.
- (f) Break down of fuse or poor contact with wire (it is easily to spoil motor while short circuit)- Switch off power source at once and replace fuse with new one. (Use identical or same specification fuse.)

(3) The temperature of spindle bearing is too hot:

- (a) Grease is insufficient- Fill the grease.
- (b) The spindle bearing is fixed too tight - Turning with no speed and feel the tightness with hand.
- (c) Turning with high speed for a long time - Turn it to lightly cutting.

(4) Lack of power with main spindle revolving:


- (a) Motor has burned out - Change a new motor.
- (b) Fuse has burned out - Replace with new one.


(5) Shake of spindle and roughness of working surface has taken place during performance:

- (a) The gap of spindle bearing too wide - Adjust the gap in proper or replace bearing with new one.
- (b) Spindle loosening up and down - Make two of inner bearing covers on the top tight each other. Do not over-tighten two inner bearing covers with the taper bearing; it is ok as long as no gap between them.
- (c) The gap of taper sliding plate too wide - Adjust the tension of bolt in proper.
- (d) Loosening of chuck - Fasten chuck.
- (e) Cutter is dull – Reshape it.
- (f) Workpiece has not hold firmly - Be sure to tighten workpiece.



12.STANDARD FEATURES- ALL MODELS

- Short Circuit Protection
- Electronic Motor Burnout Protection (1 x t)
- LED's for "Power On" and Overload (OL)
- Active Bridge: Provides controlled AC line inrush current limiting
- Power Transistor Short Circuit Runaway Protection
- Heat-Spreader: Prevents power transistor failure due to overloads
- Under Voltage Protection






19V(AC)-081009-R2



19V(AC)-081009-R2



19V(AC)-081009-R2

PARTS LIST

MODEL NO. 19V(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
1	668001D	Head Body		1	
2	668003S	Rack Sleeve Set	MT3	1	
2	668003AS	Rack Sleeve Set	MT4	1	
2-1	HCS09	C-Retainer ring		1	
2-2	CA6204ZZ	Bearing	6204ZZ	1	
2-3	668003	Rack Sleeve	MT3	1	
2-3	668003A	Rack Sleeve	MT4	1	
2-4	HCS20	C-Retainer ring		1	
2-5	CA6207ZZ	Bearing	6207ZZ	1	
2-6	668014	Spindle Shaft	MT3	1	
2-6	668014A	Spindle Shaft (For Special Request)	MT4	1	
2-7	HCR10	C-Retainer ring		1	
2-8	6119	Bearing Cap	MT3	1	
2-8	668068	Bearing Cap (For Special Request)	MT4	1	
3	668037	Rubber Flange		1	
4	668035S	Spindle Taper Sleeve Set		1	
4-1	HCS17	C-Retainer ring		1	
4-2	CA6006ZZ	Bearing	6006ZZ	2	
4-3	668036	Bearing Base		1	
4-4	668035	Spindle Taper Sleeve		1	
5	668051A	Spindle Pulley		1	
5	668051B	Spindle Pulley		1	Option
6	7102	Spindle Locknut		1	
7	HS241	Hex. Socket Head Screw	M8x15L	3	
8	668016	Pinion Shaft		1	
9	HS610	Flat Cross Head Screw	M5x10L	1	
10	HK029	Key	6x6x40L	1	
11	668022	Pinion Support		1	
12	HS229	Hex. Socket Head Screw	M6x15L	3	
13	2450051	Pin	Φ 4x13L	1	
14	61121	Limit Plate		1	
15	HH001	Rivet	Φ 2	2	
16	668033S	Graduated Dial Set		1	
17	2450051	Pin	Φ 4x13L	1	
18	2450033	Scale Base Set Screw		1	

PARTS LIST

MODEL NO. 19V(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
19	668018	Handle Body		1	
20	668024	Bushing		1	
21	HS231	Hex. Socket Head Screw	M6x25L	1	
22	2450063	Graduated Base Fixed Grip		1	
23	623121	Handle		3	
24	670010	Knob		3	
25	61105S	Spring Base Set		1	
26	690078S	Pinion Support Set		1	For CE Only
27	HS520	Cross Round Head Screw	M5x15L	3	
28	61103S	Spring Cover Set		1	
29	W202	Spring Washer	1/4"	2	
30	W004	Washer	1/4"	1	
31	HS229	Hex. Socket Head Screw	M6x15L	1	
32	HS430	Hex. Socket Headless Screw	M8x8L	4	
33	668042	Screw Key		1	
34	N005	Hex. Nut	3/8"	1	
35	668004CS	Motor Pulley Cover Assembly		1	
36	6651	Dust Plate		1	
37	HS508	Cross Round Head Screw	M4x5L	13	
38	6649	Dust Plate		1	
39	N008	Hex. Nut	5/8"	1	
40	668066AS	Fixed Shaft Set		1	
41	HK029	Key	6x6x40L	1	
42		Motor			
42	MD110	Motor	1.4KW / 110V 1PH DC130V	1	
42	MD220	Motor	1.4KW / 220V 1PH DC180V	1	
43	6650	Dust Plate		1	
44	6648	Dust Plate		1	
45	668062A	Motor Plate Base		1	
46	HS242	Hex. Socket Head Screw	M8x20L	3	
47	668045DS	Motor Pulley Assembly		1	
48	ET2519	Driver		1	
49	HW004	Washer	M6	2	
50	HS229	Hex. Socket Head Screw	M6x15L	2	
51	668041ES	Front Cover Set		1	

PARTS LIST


MODEL NO. 19V(AC)



CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
52	668069	Speed Chart		1	
53	BT370	Belt	17-370	1	
54	BT350	Belt	17-350	1	
55	HS519	Cross Round Head Screw	M5x10L	4	
57	668061A	Motor Plate		1	
58	668063A	Fixed Shaft		1	
60	HD104	Plug	§ 12	2	
62	S706	Cross Round Head Screw	3/16"x1/2"L	4	
63	HCS02	C-Retaniner Ring		2	
64	6027-1S	Knob		1	
65	HS048	Hex. Head Screw	M8x30L	2	
66	HN003	Hex. Nut	M8	2	
67	ET1627	Proximity Sensor Switch		1	
68	668067	Switch Support		1	
69	HS504	Cross Round Head Screw	M3x16L	2	
70	HS519	Round Head Screw	M5x12L	2	
71	ET2511	LCD rpm Monitor		1	
72	HS502	Cross Round Head Screw	M3x6L	4	
73	HS435	Hex. Socker Headless Screw	M8x35L	1	
74	668054S	Switch (For CE Only)		1	For Tapping Only
75	668055S	Limit Switch Support Set		1	For Tapping Only
83	668075	Bracket		1	
84	S708	Cross Round Head Screw	3/16"x3/8"L	1	
86	668088	Pinion Support		1	
87	668064A	Fixed Shaft		1	
88	6168	Punch Key		1	
89	668083	Drill Chuck	KEYLESS1/2"-JT6	1	
89	668083A	Drill Chuck	KEYLESS1/2"-B16	1	
89	668084	Drill Chuck	ALLIS JT4 1/16"-3/4"	1	Option
89	668084A	Drill Chuck	ALLIS JT3 1/16"-5/8"	1	Option
90	668050	Chuck Arbor	MT3-JT6	1	
90	668050A	Chuck Arbor	MT3-B16	1	
90	668050B	Chuck Arbor	ALLIS MT3xJT4	1	Option
90	668050C	Chuck Arbor	ALLIS MT3xJT3	1	Option
91	HS227	Hex. Socket Head Screw	M6x5L	2	

PARTS LIST


MODEL NO. 19V(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
92	668087	Shaft		1	
93	HN006	Hex. Nut	M10	1	
94	HS059	Hex. Head Screw	M10x25L	1	
95	W017	Washer		4	
96	HS242	Hex. Head Screw	M8x20L	4	
100	690045CS	Chuck Guard Asbly		1	For CE Only
100	690045DS	Chuck Guard Asbly	Option	1	For CE Only
801	668012	Swivel Base		1	
804	668007A	Column		1	
805	6610-1	Rack		1	
806	668002	Square Working Table		1	
807	HW007	Washer	M12	1	
808	668046	Lock Handle		1	
809	HN007	Hex. Nut	M12	2	
810	668026	Worm Gear		1	
811	668023	Worm Shaft		1	
812	668010	Worm Shaft		1	
813	61114	Bushing		1	
814	6158	Up-Down Handle		1	
815	S610	Hex. Socker Headless Screw	5/16"x5/16"L	1	
816	6027-1S	Clamp Handle		1	
817	HW107	Spring Washer	M12	4	
818	HS286	Hex. Socket Head Screw	M12x60L	4	
819	668080	Switch Base		1	Option
820	HT004	Round Head Screw	M5x8L	2	Option
821	ET1626	Foot Switch		1	Option
822	HT001	Round Head Screw		3	Option
823	668079	Wave Filter Protector		1	For CE Only
824	HT001	Round Head Screw	M5x8L	4	For CE Only
825	ET2510	Wave Filter		1	For CE Only
826	ET2111	Wire Nipple	PG13.5	1	Option
827	668099	Fixed Plate		2	Option
828	HT003	Round Head Screw	M6x10L	4	Option





19VTM(AC)-081009-R2



PARTS LIST

MODEL NO. 19VTM(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
1	668001D	Head Body		1	
2	668003S	Rack Sleeve Set	MT3	1	
2	668003AS	Rack Sleeve Set	MT4	1	
2-1	HCS09	C-Retainer ring	S20	1	
2-2	CA6204ZZ	Bearing	6204ZZ	1	
2-3	668003	Rack Sleeve	MT3	1	
2-3	668003A	Rack Sleeve	MT4	1	
2-4	HCS20	C-Retainer ring	S35	1	
2-5	CA6207ZZ	Bearing	6207ZZ	1	
2-6	668014	Spindle Shaft	MT3	1	
2-6	668014A	Spindle Shaft (For Special Request)	MT4	1	
2-7	HCR10	C-Retainer ring	R72	1	
2-8	6119	Bearing Cap	MT3	1	
2-8	668068	Bearing Cap (For Special Request)	MT4	1	
3	668037	Rubber Flange		1	
4	668035S	Spindle Taper Sleeve Set		1	
4-1	HCS17	C-Retainer ring	S30	1	
4-2	CA6006ZZ	Bearing	6006ZZ	2	
4-3	668036	Bearing Base		1	
4-4	668035	Spindle Taper Sleeve		1	
5	668051A	Spindle Pulley		1	
6	7102	Spindle Locknut		1	
7	HS241	Hex. Socket Head Screw	M8x15L	3	
8	668016	Pinion Shaft		1	
9	HS610	Flat Cross Head Screw	M5x10L	1	
10	HK029	Key	6x6x40L	1	
11	668022	Pinion Support		1	
12	HS229	Hex. Socket Head Screw	M6x15L	3	
13	2450051	Pin	φ 4x13L	1	
14	61121	Limit Plate		1	
15	HH001	Rivet	φ 2	2	
16	668033S	Graduated Dial Set		1	
17	2450051	Pin	φ 4x13L	1	
18	2450033	Scale Base Set Screw		1	
19	668018	Handle Body		1	
20	668024	Bushing		1	
21	HS231	Hex. Socket Head Screw	M6x25L	1	
22	2450063	Graduated Base Fixed Grip		1	
23	623121	Handle		3	

PARTS LIST

MODEL NO. 19VTM(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
24	670010	Knob		3	
25	61105S	Spring Base Set		1	
26	690078S	Pinion Support Set		1	Option
27	HS520	Cross Round Head Screw	M5x15L	3	
28	61103S	Spring Cover Set		1	
29	W202	Spring Washer	1/4"	2	
30	W004	Washer	1/4"	1	
31	HS229	Hex. Socket Head Screw	M6x15L	1	
32	HS430	Hex. Socket Headless Screw	M8x8L	4	
33	668042	Screw Key		1	
34	N005	Hex. Nut	3/8"	1	
35	668004CS	Motor Pulley Cover Assembly		1	
39	N008	Hex. Nut	5/8"	1	
40	668052DS	Fixed Shaft Set		1	
41	HK029	Key	6x6x40L	1	
42		Motor		1	
45	668062A	Motor Plate Base		1	
46	HS242	Hex. Socket Head Screw	M8x20L	3	
47	668045BS	Motor Pulley Assembly		1	
48	ET2519	Inverter	RFLF-24D	1	
49	HW004	Washer	M6	2	
50	HS229	Hex. Socket Head Screw	M6x15L	2	
51	668041BS	Front Cover Set		1	
52	668069B	Name Plate		1	
53	BT370	Belt	17-370	1	
54	BT350	Belt	17-350	1	
57	668061B	Motor Plate		1	
58	668063A	Fixed Shaft		1	
59	ET1239	Urgent Switch Button	XB5-AS542	1	
60	HD104	Plug	ϕ 12	2	
61		Electrical Box		1	
62	S706	Cross Round Head Screw	3/16"x1/2"L	4	
63	HCS02	C-Retaniner Ring	S12	2	
64	6027-1	Knob		1	
65	HS048	Hex. Head Screw	M8x30L	2	
66	HN003	Hex. Nut	M8	2	
67	ET1627	Proximity Sensor Switch		1	
68	668067	Switch Support		1	
69	HS504	Cross Round Head Screw	M3x16L	2	

PARTS LIST

MODEL NO. 19VTM(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
70	HS519	Round Head Screw	M5x12L	2	
71	ET2511	LCD rpm Monitor		1	
72	HS502	Cross Round Head Screw	M3x6L	4	
73	HS435	Hex. Socker Headless Screw	M8x35L	1	
74	668054S	Switch (For CE Only)		1	Option
75	668055S	Limit Switch Support Set		1	Option
76	HS324	Hex. Socket Head Screw	M8x90L	1	
77	HN003	Hex. Nut	M8	1	
83	668075	Bracket		1	
84	S708	Cross Round Head Screw	3/16"x3/8"L	1	
86	668088	Pinion Support		1	
87	668064A	Fixed Shaft		1	
88	6168	Punch Key		1	
89		Drill Chuck		1	
90		Chuck Arbor		1	
91	HS227	Hex. Socket Head Screw	M6x5L	2	
92	668087	Shaft		1	
93	HN006	Hex. Nut	M10	1	
94	HS059	Hex. Head Screw	M10x25L	1	
95	W017	Washer		4	
96	HS242	Hex. Head Screw	M8x20L	4	
100	690045ES	Chuck Guard Asbly(For CE Only)		1	For CE Only
101	668076A	Switch Base		1	
102	670047B	Control Box		1	
103	181995	Ground Copper Plate		1	
104	HS509	Cross Round Head Screw	MSx8L	2	
105	HS519	Cross Round Head Screw	M5x10L	6	
106	ET1514	Terminal Block		12	
107	HS503	Cross Round Head Screw	M3x10L	2	
108	670052	Wave Filte		1	
110	ET2510	Wave Filter Bracket	KBRF-300	1	
111	HS509	Cross Round Head Screw	M4x8L	2	
112	670053	Gear Box Gasket		1	
113	670050	Switch Cover		1	
114	HT010	Cross Round Head Screw	M4x8L	6	
103	ET2207	Working Lamp	380V	1	
801	668012	Swivel Base		1	
804	668007A	Column		1	
805	668011B	Rack		1	

PARTS LIST

MODEL NO. 19VTM(AC)

CODE NO	PART NO	DESCRIPTION	SPECIFICATION	QTY	NOTE
806	668002	Square Working Table		1	
807	HW007	Washer	M12	1	
808	668046	Lock Handle		1	
809	HN007	Hex. Nut	M12	2	
810	668026	Worm Gear		1	
811	668023	Worm Shaft		1	
812	668010	Worm Shaft		1	
813	61114	Bushing		1	
814	6158	Up-Down Handle		1	
815	S610	Hex. Socker Headless Screw	5/16"x5/16"L	1	
816	6027-1S	Clamp Handle		1	
817	HW107	Spring Washer	M12	4	
818	HS286	Hex. Socket Head Screw	M12x60L	4	
819	668080	Switch Base (Optional)		1	
820	HT004	Round Head Screw (Optional)	M5x8L	2	
821	ET1626	Foot Switch (Optional)		1	
822	HT001	Round Head Screw (Optional)		3	
823	668079	Wave Filter Protector (Optional)		1	
824	HT001	Round Head Screw (Optional)	M5x8L	4	
825	ET2510	Wave Filter (Optional)		1	
826	ET2111	Wire Nipple (Optional)	PG13.5	1	
827	668099	Fixed Plate		2	
828	HT003	Round Head Screw (Optional)	M6x10L	4	
829	668080	Switch Base (Optional)		1	Option
830	HT001	Round Head Screw (Optional)	M5x8L	2	Option
831	ET1626	Foot Switch (Optional)		1	Option
832	HT001	Round Head Screw (Optional)	M5x8L	3	Option
833	ET2110	Wire Nipple (Optional)	PG11	1	Option
834	668100S	Vise Handle Set		1	

MANUFACTURER:

ADDRESS:

SERIAL No.:

PLEASE WRITE DOWN THE SERIAL NO. ON THIS BLOCK FROM THE NAME
PLATE AFTER YOU RECEIVE THIS MACHINE.

WARNING

General Machinery Safety Instructions

Machinery House
requires you to read this entire Manual before using this machine.

- 1. Read the entire Manual before starting machinery.** Machinery may cause serious injury if not correctly used.
- 2. Always use correct hearing protection when operating machinery.** Machinery noise may cause permanent hearing damage.
- 3. Machinery must never be used when tired, or under the influence of drugs or alcohol.** When running machinery you must be alert at all times.
- 4. Wear correct Clothing.** At all times remove all loose clothing, necklaces, rings, jewelry, etc. Long hair must be contained in a hair net. Non-slip protective footwear must be worn.
- 5. Always wear correct respirators around fumes or dust when operating machinery.** Machinery fumes & dust can cause serious respiratory illness. Dust extractors must be used where applicable.
- 6. Always wear correct safety glasses.** When machining you must use the correct eye protection to prevent injuring your eyes.
- 7. Keep work clean and make sure you have good lighting.** Cluttered and dark shadows may cause accidents.
- 8. Personnel must be properly trained or well supervised when operating machinery.** Make sure you have clear and safe understanding of the machine you are operating.
- 9. Keep children and visitors away.** Make sure children and visitors are at a safe distance for you work area.
- 10. Keep your workshop childproof.** Use padlocks, Turn off master power switches and remove start switch keys.
- 11. Never leave machine unattended.** Turn power off and wait till machine has come to a complete stop before leaving the machine unattended.
- 12. Make a safe working environment.** Do not use machine in a damp, wet area, or where flammable or noxious fumes may exist.
- 13. Disconnect main power before service machine.** Make sure power switch is in the off position before re-connecting.
- 14. Use correct amperage extension cords.** Undersized extension cords overheat and lose power. Replace extension cords if they become damaged.
- 15. Keep machine well maintained.** Keep blades sharp and clean for best and safest performance. Follow instructions when lubricating and changing accessories.
- 16. Keep machine well guarded.** Make sure guards on machine are in place and are all working correctly.
- 17. Do not overreach.** Keep proper footing and balance at all times.
- 18. Secure workpiece.** Use clamps or a vice to hold the workpiece where practical. Keeping the workpiece secure will free up your hand to operate the machine and will protect hand from injury.
- 19. Check machine over before operating.** Check machine for damaged parts, loose bolts, Keys and wrenches left on machine and any other conditions that may effect the machines operation. Repair and replace damaged parts.
- 20. Use recommended accessories.** Refer to instruction manual or ask correct service officer when using accessories. The use of improper accessories may cause the risk of injury.
- 21. Do not force machinery.** Work at the speed and capacity at which the machine or accessory was designed.
- 22. Use correct lifting practice.** Always use the correct lifting methods when using machinery. Incorrect lifting methods can cause serious injury.
- 23. Lock mobile bases.** Make sure any mobile bases are locked before using machine.
- 24. Allergic reactions.** Certain metal shavings and cutting fluids may cause an allergic reaction in people and animals, especially when cutting as the fumes can be inhaled. Make sure you know what type of metal and cutting fluid you will be exposed to and how to avoid contamination.
- 25. Call for help.** If at any time you experience difficulties, stop the machine and call you nearest branch service department for help.

WARNING

Drilling Machine Safety Instructions

Machinery House
requires you to read this entire Manual before using this machine.

- 1. Maintenance.** Make sure the Drill is turned off and disconnect from the main power supply and make sure all moving parts have come to a complete stop before any inspection, adjustment or maintenance is carried out.
- 2. Drill Condition.** Drill must be maintained for a proper working condition. Never operate a Drill that has damaged or worn parts. Scheduled routine maintenance should be performed on a scheduled basis.
- 3. Leaving a Drill Unattended.** Always turn the Drill off and make sure all moving parts have come to a complete stop before leaving the Drill. Do not leave Drill running unattended for any reason.
- 4. Avoiding Entanglement.** Remove loose clothing, belts, or jewelry items. Never wear gloves while machine is in operation. Tie up long hair and use the correct hair nets to avoid any entanglement with the Drill spindle or moving parts.
- 5. Chuck key & wrench safety.** Always remove chuck keys, wrenches and any service tools immediately after use. Chuck keys left in the chuck can cause serious injury.
- 6. Understand the machines controls.** Make sure you understand the use and operation of all controls.
- 7. Drill bit selection.** Always use the correct Drill bit for the job you are Drilling. Make sure you use the correct shank drill bit for your drilling machine.
- 8. Secure the Drill Bit.** Properly tighten and securely lock the drill bit in the chuck.
- 9. Cutting Tool inspection.** Inspect Drill for sharpness, chips, or cracks before use. Replace any cutting tools immediately if dull, chipped or cracked. Handle new cutting tools with care. Cutting edges are very sharp and can cause lacerations.
- 10. Reversing the spindle.** Make sure the spindle has come to a complete stop before changing the direction of the spindle.
- 11. Stopping the spindle.** Do not slow or stop the spindle by using your hand.
- 12. Speed selection.** Select the appropriate speed for the type of work, material, and tool bit. Allow the Drill to reach full speed before beginning a cut.
- 13. Changing Belts for speed selection.** Always allow the machine to come to a complete stop and turn power off before changing belts. Not turning power off when changing belts can cause serious injury.
- 14. Clearing chips.** Always use a brush to clear chips. Never clear chips when the drill is running.
- 15. Power outage.** In the event of a power failure during use of the drill, turn off all switches to avoid possible sudden start up once power is restored.
- 16. Clean work area.** Keep the area around the drill clean from oil, tools, chips.
- 17. Surface/workpiece area.** Before turning the drill on, make sure the table is clear of any objects (tools, scraps, off-cuts etc.) Do not drill material that does not have a flat surface, unless a suitable support is used.
- 18. Table Lock.** Make sure the table is tightened before starting the drill.
- 19. For - Radial Drill Arm Lock.** Make sure the arm is locked before leaving or starting a radial arm drill. An unlocked radial drill arm can swing and cause serious injury.
- 20. Drilling Sheet metal.** All sheet metal should be clamped to the table before drilling.
- 21. Mounting workpieces.** Use clamps or vices to secure workpiece before drilling. Position work so you avoid drilling into table.
- 22. Guarding.** Do not operate the drill when chuck guard is removed.
- 23. Eye and hand protection.** A face shield with safety glasses is recommended. Always keep hands and fingers away from the drill bit. Never hold a workpiece in your hand while drilling. Do not wear gloves while operating the drill.
- 24. Drill operation.** Never start the drill with the drill bit pressed against the workpiece. Feed the drill evenly into the workpiece. Back the drill out of deep holes. Turn the machine off and clear chips and scrap pieces with a brush. Turn power off, remove drill bit, and clean the table before leaving the machine.
- 25. Call for help.** If at any time you experience difficulties, stop the machine and call your nearest branch service department for help.

PLANT SAFETY PROGRAM

NEW MACHINERY HAZARD IDENTIFICATION, ASSESSMENT & CONTROL

Drilling Machine

Developed in Co-operation Between A.W.I.S.A and Australia Chamber of Manufactures
This program is based upon the Australian Worksafe Standard for Plant(NOHSC:1010-1994)

Item No.	Hazard Identification	Hazard Assessment	Risk Control Strategies (Recommended for Purchase / Buyer / User)
A	ENTANGLEMENT	HIGH	Eliminate, avoid loose clothing / Long hair etc.
B	CRUSHING	LOW	Secure & support work material on drill table.
C	CUTTING, STABBING, PUNCTURING.	MEDIUM	Isolate power to machine prior to any checks or maintenance being carried out. Do not adjust or clean until the machine has fully stopped.
D	SHEARING	MEDIUM	Isolate power to machine when changing speeds or maintenance is being carried out. Make sure all guards are secured shut when machine is on.
F	STRIKING	MEDIUM	Ensure workpieces are tightly secured on machine. Wear safety glasses. For Radial Arm Drills ensure that arm is locked before drilling. Ensure correct spindle direction when drilling..
H	ELECTRICAL	MEDIUM	All electrical enclosures should only be opened with a tool that is not to be kept with the machine. Never clean or dust machine when power is on. Machine should be installed & checked by a Licensed Electrician.
M	HIGH TEMPERATURE	LOW	Wear appropriate protective clothing to prevent hot swarf.
O	OTHER HAZARDS, NOISE.	LOW	Wear hearing protection as required.
Plant Safety Program to be read in conjunction with manufactures instructions			



www.machineryhouse.com.au



www.machineryhouse.co.nz

Authorised and signed by:
Safety officer:

Manager:




Revised Date: Aug-08